## Form 9

## **Construction Act**

## **CERTIFICATE OF SUBSTANTIAL PERFORMANCE** OF THE CONTRACT UNDER SECTION 32 OF THE ACT

Ontario, Canada

(Country/Distract or Regional I	Municipality/City or Borough of Mun	icinality of Metropolitan Toronto in	which the Premises are situated)

## 415 Locust St. Burlington

	415 Locust St., Du	mington	
(Stree	t Address and city, town, or if there is no street a	ddress, the location of the premises)	
This is to certify that the contract	for the following improvement	:	
Replacement Of The Entire Wind Window Frames, Spandrel Panel,	And Balcony Door System	dential Tower Only. Including But Not Limited To	
	(short description of the imp	rovement)	
to the above premises was substantially performed on		February 9, 2024	
Date Certificate Signed:	February 9, 2024	Mhlan	
Date Continuate digited.	1 001daiy 0, 202 i	(payment certifier where there is one)	
		(owner and contractor, where there is no payment certifier)	
Name of owner	Halton Condominium Corporation No. 191		
Address for service	c/o Maple Ridge Community Management Ltd. 5753 Coopers Ave. Mississauga, ON, L4Z 1R9		
Name of Contractor	K.I.B Building Restoration Inc.		
Address for service	5320 Bradco Blvd. Mississauga, ON, L4W 1G7		
Name of payment certifier Edison Engineers Inc.			
Address	17 Ogilvie St. Dundas, ON, L9H 2S1		
(Use A or B whichever is appropriate)  A. Identification of premises for Block 25490-0001 to 25490-	•		
(Where liens attach to premises, reference to lo B. Office to which claim for lien	,	p preserve lien:	